REGION 10 UNDERGROUND STORAGE TANK INSPECTION FORM

Lead Inspector Robert Cutter Inspection Date 3/25/99	Facility# 4-260087
Agency Reps Dave Birney Facility Reps Mel	issa loos
Tribal RepsEnforcementActio	ns: FNNC#068
<u>Facility</u>	
Location Name Smitty's Conoco	
Address	· 6 s
CityState/TribeZip	
Phone 509 - 865 - 5909 GPS reading	
Owner	
Name	
Address	A.
City	
State/TribeZipPhone	ē.
<u>Operator</u>	
Name	
Address	
City	
State/Tribe Zip Phone	
	Total # of pages

Inspection-Related Notes:

Need'						
- 6 mo. CP	Test					
- 4-th Vent	- ho	tonto	than	Knor	- of."	
- FR FPA		7	/	•		
		/ 00	7 \			2007,
Talked to Sus	an Sm		10/d	of	FNNC	
and wont over c	complien	ce ite	ms.		F	
a , t _e					ga te	
	***			**		
eta a	- 2	N.		7	a 1 wile	
			*		31.00	
	1					
		ái .			e.Ai	
Second of the se						
					- university	

						. .
					Check if additional pa	ges

Tank #	1	2	3	4	5	6
	TAN	K STATU	s			
Tank cap (gal)						
Product in tank						
Date installed						
Date last used						
site assessment (y/n)						
product in tank <1" (y/n)						
FI	NANCIA	AL RESPO	NSIBILIT	Υ		
Type of FR	-1,1			1		
Date of coverage					20 82	. S
SPI	LL/OVE	RFILL (tran	nsfers>25 g	allons)		I V II
spill bucket						
ball float valve						
flow restrictor						
automatic alarm						
	LEAR	DETECT	TION			
Manual Tank Gauging						
MTG correct?(<1,000gal.) (y/n), 12months?						
MTG correct?(<2,000) (y/n)						
TTT, 12 months of records? (y/n) date?						
Inventory Control						
IC correct? 12 months of IC						
Equipment capable of measuring to nearest 1/8 "						
Water Test?						
Drop Tube?						

Tank #	1	2	3	4	5	6
Tank Tightness Tests? (Every 5yrs for 10yrs only)						
(y/n) date? P/F?						
Automatic Tank Gauging						
Console visible and properly functioning(paper						
available)?						
Adequate waiting time for test after delivery?				Α		
Testing at range of product level?				44		
Documentation of .2 gph detection and 95%					4	
confidence level ?				į	1.6 M	it.
ATG is operating in leak detection modality?				15 1 45	*	F . V.
Document monthly monitoring for last 12				40	100	ar e en
mos.including for water test?					Alter =	
Statistical Inventory Reconciliation						
SIR results reveal tank pass?						
Docmentation for last 12 months?						
Third party certification ?						
Interstitial Monitoring					-15-	
Equipment used o take readings is accessible and						
functional?						
Documentation of .2 gph detection and 95%						
confidence level?						
Documentation of last 12 months of monitoring						
Ground Water Monitoring						
Site assessment performed prior to installation						
of wells (ie: 3' <gw<20')< td=""><td></td><td></td><td></td><td></td><td></td><td></td></gw<20')<>						
Proper functioning of a manual or automatic						
device used to monitor GW monthly?						

Tank #	1 -	2	3	4	5	6
Documentation for last 12 months?						
GW well is clearly marked and secured?						
Vapor Monitoring				-		
Sit assessment prior to installation of system?						
Equipment used to take readings is accessible and functioning? Documentation for 12 mos.?						
Power box accessible and power light on?						
	PI	PING				
Suction				= /-	7 12 1 17	** 3
All of the following conditions met? operates at < latm, only one check valve directly under pump, piping sloped to tank, if so, no LD required if not see next box					egit at travelet	
Line Tightness Test (LTT) - 1×/3yr <u>or</u>						
monthly monitoring						
Pressurized						
Automatic Line Leak Detector (ALLD)w/ flow restrictor, shut off or alarm and						
Line Tightness Test (LTT) -1/yr <u>or</u>						
Monthly Monitoring Method (12 months) (ATG, GW, VP, INTSTL, SIR)						
Does o/o have 3 rd party evaluation						

Tank #	1 -6-	2	3	4	5	6
	CORR	osion i	PROTEC	TION		
corrosion resistant material fiberglass/composite?						
Tank Lining						
was an integrity inspection performed and when?						
10 year inspection after installation?						
5 yr inspection?						
Cathodic Protection						
was an integrity inspection performed and when?						
Sacrificial Anode				B8		
6 months tests after installation/3yr tests						A 199
last two test available?					.v 0.1	14
Impressed Current					21 3 11 1	Ottotal A
rectifier checked every 60 days?					S.	
last 3 test present?						
Tank#	ı	2	3	4	5	6
CORROSIO	N PROTE	CTION	(Piping)			
Fiberglass Piping or Double walled						
Fiberglass w/steel						
Cathodic Protection						
Sacrificial Anode						
6 mo. test after installation; 3yr CP test						
last 2 test available?						
Impressed Current						
rectifier checked every 60 days?						
last 3 test present?						

· 1. * ...